


Example 5-2: Determine the time it takes a fuse to melt if a current of 3 A suddenly flows through the fuse subject to the following conditions:



Given:

$$D = 0.1 \text{ mm} \quad T_{melt} = 900 \text{ }^\circ\text{C} \quad k = 20 \text{ W/mK}$$

$$L = 10 \text{ mm} \quad T_\infty = 30 \text{ }^\circ\text{C} \quad \alpha = 5 \times 10^{-5} \text{ m}^2/\text{s} \equiv k/\rho C_p$$

Assume:

- constant resistance $\mathcal{R} = 0.2 \text{ ohms}$
- the overall heat transfer coefficient is $h = h_{conv} + h_{rad} = 10 \text{ W/m}^2\text{K}$
- neglect any conduction losses to the fuse support


Solution: First, check the size of the Biot number

$$Bi = \frac{hV}{kA_s} = \frac{hD}{4k} = 1.25 \times 10^{-5} \ll 0.1$$

Therefore the lumped system approach is applicable and we can approximate $T \approx T(t)$ only.

Performing an energy balance over the fuse

$$\frac{dE_{ST}}{dt} = \dot{E}_{in} - \dot{E}_{out} + \dot{E}_g$$



where

$$\frac{dE_{ST}}{dt} = m C dT/dt$$

$$\dot{E}_{out} = hA_s(T - T_\infty)$$

$$\dot{E}_g = I^2 \mathcal{R}$$

Therefore

$$m C \frac{dT}{dt} = -hA_s(T - T_\infty) + I^2 \mathcal{R}$$

and

$$\frac{dT}{dt} = \underbrace{-\frac{hA_s}{mC}}_{-1/\tau} \left[\underbrace{T - T_\infty - \frac{I^2 \mathcal{R}}{hA_s}}_{\theta(t)} \right]$$

Collecting terms

$$\frac{d\theta}{\theta} = -\frac{1}{\tau} dt \Rightarrow \ln \theta = -\frac{t}{\tau} + C_1$$

The initial conditions are

$$@t = 0 \Rightarrow T = T_i \Rightarrow C_1 = \ln \left(T_i - T_\infty - \frac{I^2 \mathcal{R}}{hA_s} \right)$$

Therefore

$$T(t) = T_\infty + (T_i - T_\infty)e^{-t/\tau} + \frac{I^2 \mathcal{R}}{hA_s} (1 - e^{-t/\tau})$$

Using $T_i = T_\infty$ and $T(t) = T_{melt}$ we can determine the time, t for the fuse to blow out

$$900^\circ C = 30^\circ C + 5.73 \times 10^4^\circ C (1 - e^{-t})$$

Solving for t gives

$$t = 15.3 \text{ ms} \Leftarrow$$