
T
s
reduction in work input
increase in cooling capacity
$\dot{Q}_H$
$\dot{Q}$
$\dot{Q}_L$
$W_{c,B}$
$W_{c,A}$
1
2
3
4
5
6
7
8